


# Machining

ver. 1



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton

# Old Machine Shop – Edison's lab



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton




# Machining = Chip formation by a tool



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton

# Big lathe with big chips



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton




# Giant Lathe



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton




# Discontinuous chips



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton

# Continuous chips



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton


# Machine Tools and Processes

- Turning
- Boring
- Milling
- Planing
- Shaping
- Broaching
- Drilling
- Filing
- Sawing
- Grinding
- Reaming
- Honing
- Tapping



# Classification of Conventional Machining

- Cutting processes
  - Single point: e.g. shaping, planing, turning, boring, etc.
  - Multiple point: e.g. milling, drilling, etc.
- Abrasive processes
  - Grinding, honing, etc.






# Lathe (for turning)



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton


# Lathe Parts



ME 338: Manufacturing Processes II  
 Instructor: Ramesh Singh; Notes: Profs.  
 Singh/Melkote/Colton



# Typical Insert Cutting Tool






# Pillars made on Lathe





# Old Lathe




ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton







(a) Straight turning




(b) Taper turning




(c) Profiling




(d) Turning and external grooving




(e) Facing




(f) Face grooving




(g) Cutting with a form tool




(h) Boring and internal grooving




(i) Drilling




(j) Cutting off





(k) Threading





(l) Knurling



# Boring



# Old Boring Machine



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton






# Old Planer



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton




# Shaper






# Trepanning


(a)



(b)




# Drilling




# Milling



(a) Slab milling



(b) Face milling



(c) End milling



*Common HSS milling cutters.*

ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton


# Face Milling



ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton




# Horizontal Mill





# Old Horizontal Mill




ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton






# Vertical Mill




# Milling Types


(a) Straddle milling




(b) Form milling



(c) Slotting




(d) Slitting





# Ultra-High Speed Micromilling Machine in the Machine Tools Lab at IITB






ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton

28






# Broach





# Reamers




bridge reamer






# Honing



# Thread Tap and Die



internal




external




ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton




# Shaping




Facing – top  
(a)




Facing – side  
(b)



Slotting  
(c)




Steps  
(d)





# Planing



# Shaping & Planing

- Material removal rate,  $MRR = Vwt_0$
- Cutting power,  $P_c = u_c MRR$
- Machining time,  $t_m = L/V$ 
  - $L$  is the length of cut



**u** is composed of:

- $u_s$ , the shear energy per unit volume
- $u_f$ , frictional energy per unit volume
- chip curl energy
- chip acceleration kinetic energy
- surface energy of new surfaces





# Where does cutting energy go?

- 90% to chip
- 5% to tool
- 5% to workpiece



**u** can be obtained in two ways

- Tabulated
- Estimated
  - $u \sim HB$



# Cutting Energy ( $u$ )

As a first approximation:

$$u \approx u_s + u_f$$

$$u_s \approx 0.75 - 0.8 u$$

hence


$$u \approx 1.5 u_s$$



## Estimation of $u$

- Assume a simple, rigid-perfectly plastic material:

$$u_s = \int \sigma \cdot d\varepsilon = \sigma_0 \cdot \varepsilon = \tau_{fm} \cdot \gamma$$



$$\sigma_0 \approx \frac{HB}{3}$$

for heavily cold-worked metals

$$\varepsilon \approx 1 - 2 \Rightarrow \gamma \approx 2 - 4$$





## Estimation of $u$

$$\tau_{fm} \approx \frac{\sigma_o}{2} \approx \frac{1}{6} HB$$

$$u_s \approx \frac{1}{3} HB \rightarrow \frac{2}{3} HB$$



# What number to use?

From above

$$u \approx 1.5 u_s$$

$$u_s \approx (1/3 \text{ to } 2/3) \text{ HB}$$

$$u \approx (1/2 \text{ to } 1) \text{ HB}$$

so, if no data,  $u \approx \text{HB}$




# Comparison of Tensile and Cutting (Ex. 1-1)

- 304 stainless steel rod
- $d_o = 0.5$  in,  $d_f = 0.48$  in,  $l_o = 6$  in
- What is the energy required using tension?
- What is the energy required using cutting?



## Tension: Ex. 1-2

$$\int \sigma \cdot d\varepsilon_1 = u = \frac{K \cdot \varepsilon_1^{n+1}}{n+1}$$



$u \times \text{volume} = \text{Energy}$

$$K = 185,000 \text{ psi}; n = 0.45$$





## Tension - Ex. 1-3

$$\begin{aligned} \text{Energy} &= \frac{K \cdot \epsilon_1^{n+1}}{n+1} A_o l_o \\ &= \frac{(185,000) \cdot (0.0816)^{1.45}}{1.45} \pi (0.25)^2 (6) \\ &= 3,970 \text{ in} - \text{lbf} = 449 \text{ J} \end{aligned} \quad \epsilon_1 = 2 \ln \left( \frac{0.5}{0.48} \right) = 0.0816$$



## Cutting - Ex. 1-4

Energy = (specific cutting energy) \*  
(volume removed)

$$E = u \times \frac{\pi}{4} (D_i^2 - D_f^2) \cdot l$$

$$u_{ss} \approx 1.5 \text{ hp min/in}^3 \times 550 \times 60 \times 12 \\ = 594,000 \text{ in-lbf/in}^3$$

$$E = 594,000 \times \frac{\pi}{4} (0.5^2 - 0.48^2) \cdot 6$$

$$= 54,650 \text{ in-lbf (6,176 J)}$$



## Relation between $u$ and $t_0$

- As the depth of cut decreases, the surface area to volume ratio increases, hence friction (energy) increases
- Since

$$u \approx u_s + u_f$$



- Hence

$$u \propto \frac{1}{t_0}$$





# Turning -MRR



# Turning

- Average cutting speed,  $V_{avg} = \pi D_{avg} N$ 
  - $D_{avg}$  is the average diameter of workpiece
  - $N$  is the spindle speed in rpm
- Material removal rate,  $MRR = V_{avg} df$ 
  - $d$  is the depth of cut
  - $f$  is the feed (units: mm/rev or in/rev)
- Cutting power,  $P_c = u_c MRR = F_c V$ 
  - $F_c$  = Cutting force
  - $V$  = Cutting speed
- Machining time,  $t_m = L/(fN) = L/F$ 
  - $F$  is the feed rate (units: mm/min or in/min)



# Turning Power and Force- Ex. 2-1

Turning Titanium:

- speed = 1 m/s = 200 sfpm
- feed rate = 0.1 mm/rev = 0.0004" / rev
- depth of cut = 3 mm = 0.1"

What is cutting power and cutting force?





## Power - Ex. 2-2

$$u \approx 0.06 \text{ kW/cm}^3/\text{min} = 3.6 \text{ W/mm}^3/\text{sec}$$

$$\begin{aligned} \text{MRR} = Q = Vfd &= 1,000 \times 0.1 \times 3 \\ &= 300 \text{ mm}^3/\text{sec} \end{aligned}$$

$$\begin{aligned} P &= u \times \text{MRR} = 3.6 \times 300 = 1,080 \text{ W} \\ &= 1.45 \text{ hp} \end{aligned}$$




## Force - Ex. 2-3


$$\begin{aligned} F &= P/V = 1,080 \text{ W} \div 1 \text{ m/s} \\ &= 1,080 \text{ N (243 lbf)} \end{aligned}$$



# Milling



# Milling Modes






# Milling

- Cutting speed,  $V = \pi DN$ 
  - $D$  is the cutter diameter
- Material removal rate,  $MRR = fNd_a d_r = Fd_a d_r$ 
  - $d_a$  is the axial depth of cut
  - $d_r$  is the radial depth of cut
  - $f$  is the feed per revolution ( $= f_t N_t$ ;  $f_t$  is the feed per cutting edge/tooth and  $N_t$  is the number of teeth)
  - $F$  is the feed rate (in/min or mm/min)

- Cutting power,  $P_c = u_c MRR$

- Machining time,  $t_m = (L + l_c)/F$

$l_c$  is the length of the cutter's first contact with the workpiece



# Example

- A slab-milling operation is being carried out on a 25-in. long, 4-in. wide metal block ( $u = 4.3 \text{ hp-min/in}^3$ ) at a feed of 0.02 in./tooth and a depth of cut of 0.125 in. The cutter has a diameter of 4 in., has eight straight cutting teeth, is 2 inches wide and rotates at 200 rpm. Calculate the material removal rate, the cutting time, and the power required.





ME 338: Manufacturing Processes II  
Instructor: Ramesh Singh; Notes: Profs.  
Singh/Melkote/Colton

- $d_a = 24$
- $d_r = 0.125$  in
- $u = 4.7 \text{ hp min/in}^3$

•  $l_c =$

•  $F = f \cdot N \cdot v \cdot t$

$F = 0.0278 \times 200$

$$l_c = \int (D - d_r) \cdot d_r$$

$$l_c = \int (D - d_r) d_r$$





# Summary

- General Machining Process
- Shaping & planing
- Turning
- Milling

